





### Ground Anchor Work

Since 1988, high durability anchors have been standard.

Cross-sectional deficiency due to corrosion of FG steel material (old type)

Pre-1988 anchors

The slide features several diagrams: a cluster of modern anchors, a cross-section of an old anchor showing corrosion, and a world map. Text on the slide includes 'Since 1988, high durability anchors have been standard.' and 'Cross-sectional deficiency due to corrosion of FG steel material (old type)'. A small number '14' is visible in the bottom right corner of the slide.

Presenter

Participant 1

Participant 2

Participant 3

Participant 4

Participant 5

Participant 6

Participant 7

Participant 8